



## HANDLES MACHINE / CUTTING LAYOUT

### NOTES:

1. EX-----
2. ALL HOLES TO BE M6 TAPPED THREAD
3. ALL EDGES TO BE SMOOTH FINISHED
4. OUTSIDE FACE TO BE BRUSH FINISHED
5. FINAL PRODUCT TO BE ANODISED WITH 20 MICRON BLACK - BRIGHT