

Parts List for lab12 ported box x.

Part# Dimensions Name

1)	39 1/4 x 11 1/16	side
2)	39 1/4 x 11 1/16	side
3)	39 1/4 x 11 1/16	side
4)	39 1/4 x 11 1/16	side
5)	39 1/4 x 11 1/16	side
6)	39 1/4 x 11 1/16	side
7)	39 1/4 x 11 1/16	side
8)	39 1/4 x 11 1/16	side
9)	15 1/2 x 39 1/4	top-bottom
10)	15 1/2 x 39 1/4	top-bottom
11)	15 1/2 x 39 1/4	top-bottom
12)	15 1/2 x 39 1/4	top-bottom
13)	15 1/2 x 39 1/4	top-bottom
14)	15 1/2 x 39 1/4	top-bottom
15)	15 1/2 x 39 1/4	top-bottom
16)	15 1/2 x 39 1/4	top-bottom
17)	29 x 11 1/16	port
18)	29 x 11 1/16	port
19)	29 x 11 1/16	port
20)	29 x 11 1/16	port
21)	15 1/2 x 12 1/2	end cap
22)	15 1/2 x 12 1/2	end cap
23)	15 1/2 x 12 1/2	end cap
24)	15 1/2 x 12 1/2	end cap
25)	12 3/4 x 12 1/2	baffle, centered circle cutout 10.98 dia.
26)	12 3/4 x 12 1/2	baffle, centered circle cutout 10.98 dia.
27)	12 3/4 x 12 1/2	baffle, centered circle cutout 10.98 dia
28)	12 3/4 x 12 1/2	baffle, centered circle cutout 10.98 dia
29)	39 1/4 x 2	port rib
30)	39 1/4 x 2	port rib
31)	39 1/4 x 2	port rib
32)	39 1/4 x 2	port rib
33)	34 1/4 x 2	chamber rib
34)	34 1/4 x 2	chamber rib
35)	34 1/4 x 2	chamber rib
36)	34 1/4 x 2	chamber rib
37)	34 1/4 x 2	chamber rib
38)	34 1/4 x 2	chamber rib
39)	34 1/4 x 2	chamber rib
40)	34 1/4 x 2	chamber rib
41)	34 1/4 x 2	chamber rib
42)	34 1/4 x 2	chamber rib
43)	34 1/4 x 2	chamber rib
44)	34 1/4 x 2	chamber rib
45)	11 1/16 x 2	chamber horiz strut
46)	11 1/16 x 2	chamber horiz strut
47)	11 1/16 x 2	chamber horiz strut
48)	11 1/16 x 2	chamber horiz strut
49)	11 1/16 x 2	chamber horiz strut
50)	11 1/16 x 2	chamber horiz strut
51)	11 1/16 x 2	chamber horiz strut
52)	11 1/16 x 2	chamber horiz strut
53)	14 1/16 x 2	long horiz strut
54)	14 1/16 x 2	long horiz strut
55)	14 1/16 x 2	long horiz strut
56)	14 1/16 x 2	long horiz strut
57)	11 5/16 x 2	vert strut
58)	11 5/16 x 2	vert strut
59)	11 5/16 x 2	vert strut
60)	11 5/16 x 2	vert strut


61)	11 5/16 x 2	vert strut
62)	11 5/16 x 2	vert strut
63)	11 5/16 x 2	vert strut
64)	11 5/16 x 2	vert strut
65)	11 5/16 x 2	vert strut
66)	11 5/16 x 2	vert strut
67)	11 5/16 x 2	vert strut
68)	11 5/16 x 2	vert strut

Material List for lab12 ported box x4.txt


1)	48 x 96
2)	48 x 96
3)	48 x 96

Cutting Diagram for lab12 ported box x4.txt

Supply piece 1



Supply piece 2



Cutting Diagram for lab12 ported box x4.txt

Supply piece 3

