


Not inverting preamp

$Z_{in}=47\text{Kohm}$ $BW-3\text{dB}= 5\text{Hz} - 140\text{Khz}$



Draw to Mauro Penasa