

Plus
from
Preregulator

LM317

Alternative
to BD140 =
2SA1381
has different PinOut

LM317
BD140-16
have to be
cooled



