



SW1, SW2 = Input Capacitance (Left + Right)			
Set SW1 = SW2			
(-- = OFF)			
1	2	3	
--	--	--	= 0 pF (Only Cable Capacitance)
ON	--	--	= 22 pF
--	ON	--	= 47 pF
ON	ON	--	= 69 pF
--	--	ON	= 100 pF
ON	--	ON	= 122 pF
--	ON	ON	= 147 pF
ON	ON	ON	= 169 pF



- H1 MountingHole
- H2 MountingHole
- H3 MountingHole
- H4 MountingHole



Ansible – Diyaudio.com

Sheet: /
File: RIAA-Pre_1656_01.kicad_sch

Title: RIAA-Pre_1656_01

Size: A4 Date: 2025-03-30

KiCad E.D.A. 8.0.8

Rev: 0.1

Id: 1/1