

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>DTS4067</b> (Cont'd) PTC10000 3 PTC ST10000 3 STI SVT6060 3 TRWS	<b>E100</b> (Cont'd) TMPF5950 3 SPR TP5950 3 SPR	<b>E108</b> J105 1 INL J108-18 1 NSC	<b>E114</b> (Cont'd) 2N5247 3 IFC 2N5555 3 INL MPF4393 3 MOTA THJ5486 3 SPR TMPF5486 3 SPR	<b>E210</b> (Cont'd) THJJ210 3 SPR TMPF5397 3 SPR MPF5484 3 SPR TMPFJ210 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>E270</b> (Cont'd) TMPFJ270 3 SPR
<b>DTS4072</b> GE5062 1 GESY ST14072 1 STI MJ10001 3 MOTA PTC10000 3 PTC	<b>E101</b> 2N5457 1 MOTA A5T3821 1 IFC J201-18 1 SIX J204 1 INL 2N3821 3 NSC SIX 2N5484 3 INL 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE J201 3 INL J305 3 SIX THJ5457 3 SPR TMPF5457 3 SPR	MPF4391 1 MOTA ITE4391 1 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ105 3 SPR TPJ105 3 SPR	<b>E114A</b> MPF4393 1 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX	<b>E211</b> 2N5397 1 INL 2N5485 1 MOTA J211 1 SIX J211-18 1 NSC 2N5245 3 IFC DE451 3 DGE DE452 3 DGE THJ5397 3 SPR THJ5485 3 SPR THJJ211 3 SPR TMPF5397 3 SPR TMPF5485 3 SPR TMPFJ211 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>E271</b> J271 1 INL J271-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4092 3 MOTA P1086 3 NSC SIX THJJ271 3 SPR TMPFJ271 3 SPR
<b>DTS4074</b> GE5062 1 GESY MJ10004 1 MOTA PTC8000 1 PTC ST14074 1 STI GE6000 3 GESY GE10004 3 GESY IR6000 3 INR MJ10001 3 MOTA PTC10000 3 PTC PTC10004 3 PTC ST10004 3 STI SVT6000 3 TRW SVT6060 3 TRWS	<b>E102</b> 2N5457 1 INL 2N5953 1 IFC J202-18 1 NSC SIX 2N5484 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 NSC SIX BF245A 3 PHIN DE451 3 DGE J202 3 INL J305 3 SIX SX3819 3 MOTA THJ5457 3 SPR THJ5953 3 SPR TIS58 3 TI TMPF5457 3 SPR TMPF5953 3 SPR TP5953 3 SPR	MPF4391 1 MOTA ITE4391 1 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ106 3 SPR TPJ106 3 SPR	<b>E174</b> J174 1 INL J174-18 1 NSC SIX MPF970 1 MOTA J174 3 MOTA SIX J175 3 INL P1086 3 NSC THJJ174 3 SPR TMPFJ174 3 SPR	<b>E212</b> 2N5397 1 INL 2N5486 1 MOTA J212 1 SIX J212-18 1 NSC 2N5247 3 IFC DE452 3 DGE THJ5397 3 SPR THJ5486 3 SPR THJJ212 3 SPR TMPF5397 3 SPR TMPF5486 3 SPR TMPFJ212 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>E300</b> 2N5245 1 IFC 2N5397 1 INL 2N5486 1 MOTA J300 1 SIX J300-18 1 NSC SIX 2N5245-18 3 SIX 2N5247 3 IFC 2N5248-18 3 NSC DE129 3 DGE DE452 3 DGE ITE4416 3 INL MPF4093 3 MOTA PN4416 3 SIX THJ5245 3 SPR THJ5397 3 SPR THJ5486 3 SPR TMPF5245 3 SPR TMPF5397 3 SPR TMPF5486 3 SPR TP5245 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX
<b>DTS4075</b> GE5062 1 GESY MJ10004 1 MOTA PTC6001 1 PTC ST14075 1 STI GE6001 3 GESY GE10004 3 GESY IR4039 3 INR IR6001 3 INR MJ10001 3 MOTA PTC10000 3 PTC PTC10004 3 PTC ST10004 3 STI SVT6001 3 TRW SVT6060 3 TRWS	<b>E103</b> 2N5459 1 INL 2N5950 1 IFC J105-18 1 SIX J203-18 1 NSC SIX 2N5486 3 INL 2N5639 3 MOTA 2N5950-18 3 NSC SIX 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE J105 3 INL J203 3 INL MFE2012 3 MOTA PN4416 3 SIX THJ5459 3 SPR THJ5950 3 SPR TMPF5459 3 SPR TMPF5950 3 SPR TP5950 3 SPR	MPF4391 1 MOTA TIS73 1 IFC 2N5638 3 MOTA ITE4391 3 INL PN4391 3 NSC SIX PN4391-18 3 SIX SD1117BD 3 TOP THJJ111 3 SPR	<b>E175</b> J175 1 INL J175-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 MOTA P1086 3 NSC THJJ175 3 SPR TMPFJ175 3 SPR	<b>E230</b> 2N4867 1 INL 2N5457 1 MOTA J230-18 1 SIX PN3821-18 1 NSC 2N4220A 3 MOTA 2N4339 3 NSC SIX 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE DE459 3 DGE THJ4867 3 SPR THJ5457 3 SPR TMPF4867 3 SPR TMPF5457 3 SPR TP4867 3 SPR	<b>E304</b> 2N5486 1 INL J304 1 SIX J304-18 1 NSC 2N5247 3 IFC THJ5486 3 SPR THJJ304 3 SPR TMPF5486 3 SPR TMPFJ304 3 SPR
<b>DU4339</b> 2N5397 1 INL MP842 1 MPS U235 1 SIX 2N5045 3 IFC 2N5523 3 INL DE452 3 DGE THJ5397 3 SPR TMPF5397 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX	<b>E105</b> J105 1 INL J105-18 1 SIX MPF4391 1 MOTA ITE4391 3 INL MFE2012 3 MOTA PN4416 3 SIX THJ5459 3 SPR THJ5950 3 SPR TMPF5459 3 SPR TMPF5950 3 SPR TP5950 3 SPR	<b>E111</b> J111 1 INL J111-18 1 NSC SIX MPF4391 1 MOTA TIS73 1 IFC 2N5638 3 MOTA ITE4391 3 INL PN4391 3 NSC SIX PN4391-18 3 SIX SD1117BD 3 TOP THJJ111 3 SPR	<b>E176</b> J176 1 INL J176-18 1 NSC SIX MPF971 1 MOTA J175 3 SIX J176 3 MOTA P1087 3 NSC SIX THJJ176 3 SPR TMPFJ176 3 SPR	<b>E231</b> 2N4868 1 INL 2N5458 1 MOTA J231-18 1 SIX PN3684-18 1 NSC 2N3459 3 NSC SIX 2N4220A 3 MOTA 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE DE459 3 DGE THJ4868 3 SPR THJ5458 3 SPR TMPF4868 3 SPR TMPF5458 3 SPR TP4868 3 SPR	<b>E305</b> 2N5484 1 INL 2N5485 1 MOTA J305 1 SIX J305-18 1 NSC 2N5245 3 IFC 2N5246 3 IFC DE180 3 DGE DE451 3 DGE THJ5484 3 SPR THJ5485 3 SPR THJJ305 3 SPR TMPF5484 3 SPR TMPF5485 3 SPR TMPFJ305 3 SPR
<b>DU4340</b> 2N5047 1 IFC 2N5398 1 INL MP842 1 MPS U235 1 SIX 2N5045 3 IFC 2N5454 3 INL 2N5523 3 INL BF521 3 PHIN MP845 3 MPS THJ5047 3 SPR THJ5398 3 SPR TMPF5398 3 SPR TP5398 3 SPR U309 3 MOTA U312 3 SIX	<b>E106</b> J106 1 INL J106-18 1 SIX J108-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ106 3 SPR TPJ106 3 SPR	<b>E112</b> J112 1 INL J112-18 1 NSC SIX MPF4392 1 MOTA TIS74 1 IFC 2N5639 3 MOTA ITE4392 3 INL PN4392 3 SIX PN4392-18 3 SIX SD1107BD 3 TOP THJJ112 3 SPR TMPFJ112 3 SPR	<b>E201</b> 2N5457 1 MOTA J201 1 INL J201-18 1 NSC SIX 2N5953 3 IFC BF245A 3 PHIN DE451 3 DGE THJ5457 3 SPR THJJ201 3 SPR TMPF5457 3 SPR TMPFJ201 3 SPR	<b>E232</b> 2N4869 1 INL 2N5459 1 MOTA J203-18 1 NSC J232-18 1 SIX 2N4221 3 MOTA 2N4341 3 NSC SIX 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE DE459 3 DGE J203 3 INL THJ4869 3 SPR THJ5459 3 SPR TMPF4869 3 SPR TMPF5459 3 SPR TP4869 3 SPR	<b>E306</b> J308 1 INL SIX J308-18 1 NSC U308 1 MOTA THJJ308 3 SPR THJJ308 3 SPR TMPFJ308 3 SPR TMPFU308 3 SPR TPJ308 3 SPR TPU308 3 SPR
<b>DV1006</b> MRF137 1 MOTA	<b>E107</b> J107 1 INL J107-18 1 SIX J108-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ107 3 SPR TPJ107 3 SPR	<b>E113</b> J113 1 INL J113-18 1 NSC SIX MPF4393 1 MOTA TIS75 1 IFC 2N5640 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ113 3 SPR TMPFJ113 3 SPR	<b>E202</b> 2N5458 1 MOTA J202 1 INL J202-18 1 NSC SIX 2N5952 3 IFC BF245B 3 PHIN DE451 3 DGE THJ5458 3 SPR THJJ202 3 SPR TMPF5458 3 SPR TMPFJ202 3 SPR	<b>E272</b> J270 1 INL J270-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ270 3 SPR	<b>E307</b> J309 1 INL SIX J309-18 1 NSC U309 1 MOTA THJJ309 3 SPR THJJ309 3 SPR TMPFJ309 3 SPR TMPFU309 3 SPR TPJ309 3 SPR TPU309 3 SPR
<b>DV1007</b> MRF171 1 MOTA	<b>E108</b> J108 1 INL J108-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ108 3 SPR TPJ108 3 SPR	<b>E114</b> J114 1 INL J114-18 1 NSC SIX MPF4393 1 MOTA TIS76 1 IFC 2N5641 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ114 3 SPR TMPFJ114 3 SPR	<b>E203</b> 2N5459 1 MOTA J203 1 INL J203-18 1 NSC SIX 2N5951 3 IFC BF245C 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ203 3 SPR TMPF5459 3 SPR TMPFJ203 3 SPR	<b>E273</b> J271 1 INL J271-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ271 3 SPR	<b>E308</b> J310 1 INL SIX J310-18 1 NSC U310 1 MOTA THJJ310 3 SPR THJJ310 3 SPR TMPFJ310 3 SPR TMPFU310 3 SPR TPJ310 3 SPR TPU310 3 SPR
<b>DV1008</b> MRF172 1 MOTA	<b>E109</b> J109 1 INL J109-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ109 3 SPR TPJ109 3 SPR	<b>E115</b> J115 1 INL J115-18 1 NSC SIX MPF4393 1 MOTA TIS77 1 IFC 2N5642 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ115 3 SPR TMPFJ115 3 SPR	<b>E204</b> J204 1 INL J204-18 1 NSC SIX 2N5397 1 INL 2N5484 1 MOTA J210 1 SIX J210-18 1 NSC 2N5246 3 IFC DE180 3 DGE DE452 3 DGE THJ5397 3 SPR THJ5484 3 SPR	<b>E274</b> J272 1 INL J272-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ272 3 SPR	<b>E309</b> J311 1 INL SIX J311-18 1 NSC U311 1 MOTA THJJ311 3 SPR THJJ311 3 SPR TMPFJ311 3 SPR TMPFU311 3 SPR TPJ311 3 SPR TPU311 3 SPR
<b>DV1009</b> MRF173 1 MOTA	<b>E110</b> J110 1 INL J110-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ110 3 SPR TPJ110 3 SPR	<b>E116</b> J116 1 INL J116-18 1 NSC SIX MPF4393 1 MOTA TIS78 1 IFC 2N5643 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ116 3 SPR TMPFJ116 3 SPR	<b>E205</b> 2N5459 1 MOTA J205 1 INL J205-18 1 NSC SIX 2N5951 3 IFC BF245D 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ205 3 SPR TMPF5459 3 SPR TMPFJ205 3 SPR	<b>E275</b> J273 1 INL J273-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ273 3 SPR	<b>E310</b> J312 1 INL SIX J312-18 1 NSC U312 1 MOTA THJJ312 3 SPR THJJ312 3 SPR TMPFJ312 3 SPR TMPFU312 3 SPR TPJ312 3 SPR TPU312 3 SPR
<b>DV1010</b> MRF174 1 MOTA	<b>E111</b> J111 1 INL J111-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ111 3 SPR TPJ111 3 SPR	<b>E117</b> J117 1 INL J117-18 1 NSC SIX MPF4393 1 MOTA TIS79 1 IFC 2N5644 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ117 3 SPR TMPFJ117 3 SPR	<b>E206</b> 2N5459 1 MOTA J206 1 INL J206-18 1 NSC SIX 2N5951 3 IFC BF245E 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ206 3 SPR TMPF5459 3 SPR TMPFJ206 3 SPR	<b>E276</b> J274 1 INL J274-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ274 3 SPR	<b>E311</b> J313 1 INL SIX J313-18 1 NSC U313 1 MOTA THJJ313 3 SPR THJJ313 3 SPR TMPFJ313 3 SPR TMPFU313 3 SPR TPJ313 3 SPR TPU313 3 SPR
<b>DV1011</b> MRF175 1 MOTA	<b>E112</b> J112 1 INL J112-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ112 3 SPR TPJ112 3 SPR	<b>E118</b> J118 1 INL J118-18 1 NSC SIX MPF4393 1 MOTA TIS80 1 IFC 2N5645 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ118 3 SPR TMPFJ118 3 SPR	<b>E207</b> 2N5459 1 MOTA J207 1 INL J207-18 1 NSC SIX 2N5951 3 IFC BF245F 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ207 3 SPR TMPF5459 3 SPR TMPFJ207 3 SPR	<b>E277</b> J275 1 INL J275-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ275 3 SPR	<b>E312</b> J314 1 INL SIX J314-18 1 NSC U314 1 MOTA THJJ314 3 SPR THJJ314 3 SPR TMPFJ314 3 SPR TMPFU314 3 SPR TPJ314 3 SPR TPU314 3 SPR
<b>DV1012</b> MRF176 1 MOTA	<b>E113</b> J113 1 INL J113-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ113 3 SPR TPJ113 3 SPR	<b>E119</b> J119 1 INL J119-18 1 NSC SIX MPF4393 1 MOTA TIS81 1 IFC 2N5646 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ119 3 SPR TMPFJ119 3 SPR	<b>E208</b> 2N5459 1 MOTA J208 1 INL J208-18 1 NSC SIX 2N5951 3 IFC BF245G 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ208 3 SPR TMPF5459 3 SPR TMPFJ208 3 SPR	<b>E278</b> J276 1 INL J276-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ276 3 SPR	<b>E313</b> J315 1 INL SIX J315-18 1 NSC U315 1 MOTA THJJ315 3 SPR THJJ315 3 SPR TMPFJ315 3 SPR TMPFU315 3 SPR TPJ315 3 SPR TPU315 3 SPR
<b>DV1013</b> MRF177 1 MOTA	<b>E114</b> J114 1 INL J114-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ114 3 SPR TPJ114 3 SPR	<b>E120</b> J120 1 INL J120-18 1 NSC SIX MPF4393 1 MOTA TIS82 1 IFC 2N5647 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ120 3 SPR TMPFJ120 3 SPR	<b>E209</b> 2N5459 1 MOTA J209 1 INL J209-18 1 NSC SIX 2N5951 3 IFC BF245H 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ209 3 SPR TMPF5459 3 SPR TMPFJ209 3 SPR	<b>E279</b> J277 1 INL J277-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ277 3 SPR	<b>E314</b> J316 1 INL SIX J316-18 1 NSC U316 1 MOTA THJJ316 3 SPR THJJ316 3 SPR TMPFJ316 3 SPR TMPFU316 3 SPR TPJ316 3 SPR TPU316 3 SPR
<b>DV1014</b> MRF178 1 MOTA	<b>E115</b> J115 1 INL J115-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ115 3 SPR TPJ115 3 SPR	<b>E121</b> J121 1 INL J121-18 1 NSC SIX MPF4393 1 MOTA TIS83 1 IFC 2N5648 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ121 3 SPR TMPFJ121 3 SPR	<b>E210</b> 2N5459 1 MOTA J210 1 INL J210-18 1 NSC SIX 2N5951 3 IFC BF245I 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ210 3 SPR TMPF5459 3 SPR TMPFJ210 3 SPR	<b>E280</b> J278 1 INL J278-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ278 3 SPR	<b>E315</b> J317 1 INL SIX J317-18 1 NSC U317 1 MOTA THJJ317 3 SPR THJJ317 3 SPR TMPFJ317 3 SPR TMPFU317 3 SPR TPJ317 3 SPR TPU317 3 SPR
<b>DV1015</b> MRF179 1 MOTA	<b>E116</b> J116 1 INL J116-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ116 3 SPR TPJ116 3 SPR	<b>E122</b> J122 1 INL J122-18 1 NSC SIX MPF4393 1 MOTA TIS84 1 IFC 2N5649 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ122 3 SPR TMPFJ122 3 SPR	<b>E211</b> 2N5459 1 MOTA J211 1 INL J211-18 1 NSC SIX 2N5951 3 IFC BF245J 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ211 3 SPR TMPF5459 3 SPR TMPFJ211 3 SPR	<b>E281</b> J279 1 INL J279-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ279 3 SPR	<b>E316</b> J318 1 INL SIX J318-18 1 NSC U318 1 MOTA THJJ318 3 SPR THJJ318 3 SPR TMPFJ318 3 SPR TMPFU318 3 SPR TPJ318 3 SPR TPU318 3 SPR
<b>DV1016</b> MRF180 1 MOTA	<b>E117</b> J117 1 INL J117-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ117 3 SPR TPJ117 3 SPR	<b>E123</b> J123 1 INL J123-18 1 NSC SIX MPF4393 1 MOTA TIS85 1 IFC 2N5650 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ123 3 SPR TMPFJ123 3 SPR	<b>E212</b> 2N5459 1 MOTA J212 1 INL J212-18 1 NSC SIX 2N5951 3 IFC BF245K 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ212 3 SPR TMPF5459 3 SPR TMPFJ212 3 SPR	<b>E282</b> J280 1 INL J280-18 1 NSC SIX MPF970 1 MOTA J174 3 SIX J175 3 INL MPF4093 3 MOTA P1086 3 NSC SIX THJJ280 3 SPR	<b>E317</b> J319 1 INL SIX J319-18 1 NSC U319 1 MOTA THJJ319 3 SPR THJJ319 3 SPR TMPFJ319 3 SPR TMPFU319 3 SPR TPJ319 3 SPR TPU319 3 SPR
<b>DV1017</b> MRF181 1 MOTA	<b>E118</b> J118 1 INL J118-18 1 NSC SIX MPF4391 1 MOTA ITE4391 3 INL MFE2010 3 MOTA MFE2012 3 MOTA PN4391 3 NSC SIX PN4391-18 3 SIX THJJ118 3 SPR TPJ118 3 SPR	<b>E124</b> J124 1 INL J124-18 1 NSC SIX MPF4393 1 MOTA TIS86 1 IFC 2N5651 3 MOTA ITE4393 3 INL PN4393 3 SIX PN4393-18 3 SIX THJJ124 3 SPR TMPFJ124 3 SPR	<b>E213</b> 2N5459 1 MOTA J213 1 INL J213-18 1 NSC SIX 2N5951 3 IFC BF245L 3 PHIN DE451 3 DGE THJ5459 3 SPR THJJ213 3 SPR TMPF5459 3 SPR TMPFJ21		