


DC Servo - if used, replace C15 and C16 with a jumper, R11 and R12 with 33K and R9 and R10 with 12K



L1 and L2 are 1mm Cu1 10 turns on 4R7/2W resistor

Muting on PWR on/off

Title		
Size B	Number	Revision
Date: 11/15/2007	Sheet of	
File: C:\Documents and Settings\...STKDC SCHIDOWN By:		