

Power Transformer Wire: outside diameter 2mm (15awg) ofc silver plated ptfe wire

4pcs 1.2mt wire

4pcs 1.3mt wire

4pcs 2.5mt wire

Total 20mm wire

Winding Technique: twisted quadflar interleaved (quadflar section primer-second1-primer-second2)

How To Winding :

Divide the core in two in the middle.

First 7 turns from the quadflar wire in half, 7 more returns on it.

Fill half of the core, and do the same for the other half of core.

Create the terminals by making the necessary parallel and serial connections.

L1 Lossless Snubber Coil :

1.5 meter 0.8mm standart coil wire 40 turn 250uh

Massive Magnetics		
flyback windings		
Veysel Arslan	Rev 1.0	Page # or name
	29.11.2021	