

Excel Export Setup File Parameters

Run Name: 10328-SO2594-1-XT4117-11.2896M  
Path: \\Srv2\production\Thermal Run Data\  
Print: All Operator:  
Run Start: 15-Feb-2017 8:30 am  
S&A W2200 Rev: 6.52 Report: 2.21  
Ref F: F @ 25.00°C (Actual)  
Run Finish: 15-Feb-2017 9:18 am  
Setup File:  
\\Srv2\Production\QCC for all\FABO\XT4117.qcc

CL: 16.5pF

Crystal ID	Serial #	FL ±5 ppm	RR Ohms	C0 pF	C1 fF	Q >100 k	F/T ppm	IT1 °C	ANGL '
A001	1	-0.8	9.1	2.58	12.145	127	1.0	25.5	0.65
A003	2	-2.0	10.6	2.66	11.477	116	1.2	22.3	0.54
A004	3	-2.3	8.7	2.75	12.419	130	1.1	24.7	0.83
A005	4	-1.9	9.3	2.77	12.361	122	1.8	22.4	1.11
A006	5	-1.8	9.1	2.80	12.648	122	-2.4	28.1	1.21
A007	6	-0.5	8.2	2.74	11.545	148	-1.0	25.2	0.90
A009	7	-2.3	10.6	2.73	11.546	115	0.7	26.5	0.76
A010	8	-0.0	9.6	2.70	11.476	128	-1.5	28.2	1.09
A011	9	-0.4	7.7	2.81	12.687	145	2.0	23.0	1.38
A012	10	0.9	9.1	2.76	11.687	132	-1.2	24.1	1.05
A013	11	2.0	10.8	2.68	11.694	112	-0.8	28.0	0.80
A014	12	-3.0	10.3	2.71	12.132	113	-1.6	28.4	1.01
A015	13	0.5	10.2	2.71	12.016	115	-0.7	23.5	0.40
A018	14	-3.6	9.5	2.68	12.199	122	0.9	25.9	0.90
A019	15	-1.3	8.1	2.70	12.124	144	1.1	24.4	1.06
A020	16	-2.6	10.3	2.76	12.479	110	1.2	26.6	0.67
A022	17	4.7	8.9	2.97	12.875	123	-0.6	25.4	0.44
A023	18	-4.7	8.8	2.79	11.766	136	-1.3	25.1	1.07
A026	19	1.0	9.4	2.59	11.867	127	-1.5	25.2	1.35