

Excel Export Setup File Parameters

Run Name: 10449-SO2594-9-XT4381-90.3168M
Path: \\Srv2\production\Thermal Run Data\
Print: All Operator:
Run Start: 27-Mar-2017 8:51 am
S&A W2200 Rev: 6.60 Report: 2.21
Ref F: F @ 82.50°C (Actual)
Run Finish: 27-Mar-2017 9:57 am
Setup File:
\\Srv2\production\QCC for all\FABO\XT4381.qcc

CL: 16.5pF

Crystal ID	FL ±3 ppm	RR 60 Ohms	C0 pF	C1 fF	Q 100 k	TP1 75-90 °C	IT1 °C	ANGL '
A001	0.2	44.0	2.71	0.290	138	83.6	103.1	1.49
A002	0.2	42.8	2.86	0.304	136	84.2	104.5	1.61
A003	-2.9	42.8	2.81	0.298	138	87.0	103.2	1.05
A004	2.3	45.2	2.83	0.284	137	84.0	104.4	1.63
A005	1.5	45.2	2.89	0.294	132	82.5	102.9	1.68
A006	-2.7	42.8	2.87	0.301	137	77.1	104.3	2.88
A007	0.1	46.1	2.85	0.284	135	81.8	103.9	1.95
A008	0.6	42.9	2.89	0.298	138	86.9	103.7	1.14
A009	0.7	43.4	2.85	0.294	138	81.1	102.5	1.84
A010	0.6	41.9	2.88	0.307	137	82.7	103.9	1.80