

**TABLE B- RESULTS OF DISTORTION MEASUREMENTS @10 VOLTS RMS OUTPUT**

<b>CONDITION/HARMONIC</b>	<b>2nd</b>	<b>3rd</b>
<b>6SN7GT with 36.5 K LOAD</b>	<b>-47.8</b>	<b>-67.4</b>
<b>6SN7GT with 6SN7GT LOAD</b>	<b>-49.1</b>	<b>-67.8</b>
<b>6SN7GT with 6SN7GT ACTIVE LOAD</b>	<b>-54.1</b>	<b>-66.8</b>
<b>6BL7GT with 36.5 K LOAD</b>	<b>-48.4</b>	<b>-67.5</b>
<b>6BL7GT with 6BL7GT LOAD</b>	<b>-50.1</b>	<b>-67.3</b>
<b>6BL7GT with 6BL7GT ACTIVE LOAD</b>	<b>-54.9</b>	<b>-68.7</b>